

Express Oil Change – Ocean Springs MS

East of 3701 Bienville Blvd

Ocean Springs, MS 39564

Bid Qualifications:

Please include specific unit costs for the following items:

1. Soil at building should be compacted per Geotech Report.
2. Base bid should include the attached chain hoists in lieu of the specified model. The door installer MUST be factory certified by the door manufacturer.
3. Please include pricing for the French drain system around the oil pit that ties into the storm drain system.
4. Price pit excavation separately from other work.
5. Cut and haul of unsuitable soils
6. Import fill and compaction